pproved Release 2005/02/10 : CIA-RDP75B05759R000400040009-5

0-28-200556-8

Copy 8 of 9 copies

20 May 1968

This document contains

3 pages.

EVALUATION SUMMARY

Mission BX-6858

1. Processing and Titling -

Good (Field)

2. Physical Condition -

Good

3. Hypo Retention

Negligible

4. Exposure (based on density) -

Medium

- 5. General Comments:
 - A. Dye retention noted throughout. Entire mission was reprocessed to remove the dye.
 - B. A few kinks, pinholes and some embedded dirt noted throughout the mission.
 - C. Two parts (1,5) required retitling. The titling was removed during the dye removal process.
 - D. Several mylar splices were noted throughout the mission. Two ultrasonic splices (Frames 18 and 775) were also noted.
 - E. The clock appears in the format area on a few frames.
 - F. Bulls-eye targets appear intermittently in the format.

Page 1

MISSION NO.BX-6858 EVALUATION REPORT

Evaluated By	yQ.C.	Technicians	Camera	Fwd/Aft
Evaluation 1	Date 9 N	ay 1968	Emulsion	3404

Film Metering Good

Film Tracking Fair to good

Clock Operation Exposure Normal

Counter Operation Operational

Data Chamber (image quality) Good

Apparent Resolution Normal

Apparent Granularity Normal

Density Medium

Contrast Medium

Discrepancies:

<u>Part</u>	<u>Frames</u>	Comments
1	1-75	Emulsion scratch
2	77-151	Emulsion scratch
3	152-227	Plus density streak
4	229-304	Emulsion scratch
5	306-379	Intermittent emulsion scratch
6		
7	468,490	Plus density streak
8	537,540	Emulsion scratch
9	609-684 610	Emulsion scratch Abrasions
10	753 756	Emulsion scratch Emulsion pickoff

Page 2

Discrepancies (Cont'd) Camera

Part	Frames	Comments
11		
12		
13	926 923	Crease Emulsion pickoff
14	990 995	Handling marks Transverse plus density streak
15	1139 1140	Handling marks, crease Abrasions
16		
17	1217-1292	Emulsion scratch
18		
19	1343,1344,1370	Emulsion scratch
20	1446-1458	Abrasions, emulsion scratches